

DISTRIBUTION OF QUANTITIES

Table of Contents - Distribution of Quantities

Project Name - Louisquisset Pike Bridge 074801 & 074821 Girder Repairs
Estimate Name - Louisquisset Pike Bridge 074801 & 074821 Girder Repairs
R.I. Contract No. - 2021-CB-013
FAP Nos: BHO-0748(002)

ItemCode	Description	Page
824.9901	TYPE 2, TYPE 2A STRUCTURAL STEEL WELD REPAIRS	1
824.9910	TYPE 1 STEEL BEAM GIRDER REPAIR	1
824.9925	R&D, REPLACE BUILT-UP CROSS BRACE DIAPHRAGMS	1
936.0100	MOBILIZATION AND DEMOBILIZATION	1

Distribution of Quantities

Project Name - Louisquisset Pike Bridge 074801 & 074821 Girder Repairs
 Estimate Name - Louisquisset Pike Bridge 074801 & 074821 Girder Repairs
 R.I. Contract No. - 2021-CB-013
 FAP Nos: BHO-0748(002)

Item No.	Item Code	Description	UM	Qty.	Pay Code	Seq. No.
001	824.9901	TYPE 2, TYPE 2A STRUCTURAL STEEL	EACH			
		WELD REPAIRS				
		BRIDGE				
		BRIDGE		5.00	0014	01
		Item 824.9901 Total:		5.00		
002	824.9910	TYPE 1 STEEL BEAM GIRDER REPAIR	LBS			
		BRIDGE				
		BRIDGE		895.00	0014	01
		Item 824.9910 Total:		895.00		
003	824.9925	R&D, REPLACE BUILT-UP CROSS BRACE	LBS			
		DIAPHRAGMS				
		BRIDGE				
		BRIDGE		1,740.00	0014	01
		Item 824.9925 Total:		1,740.00		
004	936.0100	MOBILIZATION AND DEMOBILIZATION	LS			
		BRIDGE				
		BRIDGE		1.00	0014	01
		Item 936.0100 Total:		1.00		