

ADDENDUM NOTIFICATION

Project Title:

General Structural Repairs / Replacement Task Order Program

Project Name: Ashton Viaduct Repairs – Bridge No. 027501

RIC No.: 2025-CB-065

FAP No.: BHO-0275(003)

Addendum No.: 1

Bid Opening Date: October 14, 2025

Notice to Prospective Bidders

In accordance with the issuance of **Addendum No. 1**, all prospective bidders and interested parties are hereby notified of the following revisions to the Contract Specifications. These revisions shall be incorporated into the Contract Documents and shall constitute an integral part of the Contract.

Specification Revisions

1. Sequence of Construction and Schedule

- **Work Restrictions:**

No work shall be performed on the bridge between March 15, 2026 and July 15, 2026 due to restrictions under the Migratory Bird Treaty Act.

- **Section 108.03 Prosecution and Progress:**

A minimum of 3 repair areas of the non-temperature-sensitive work, including but not limited to; survey/field measurements, supplemental support for precast floorbeam cantilever brackets, and supplemental support for precast concrete spandrel arch beams; must be completed by March 1, 2026. The spandrel arch repair Area #4 in Span #6 shall be prioritized and started first. The Contractor shall perform temperature-sensitive work only between July 15, 2026 and Substantial Completion, or as otherwise permitted in accordance with the RIDOT Standard Specifications.

Failure to complete the above noted non-temperature-sensitive work by March 1, 2026 shall result in an assessment of fines in the amount of \$2,500 per calendar day beyond this date until such work is completed.

2. Access to Work Areas

Effective **July 31, 2026**, all access to work areas shall be **from above the bridge**. Access from beneath the bridge will not be permitted from **July 31, 2026** through **Substantial Completion**.

3. Substantial Completion Date

The **Substantial Completion Date** for this contract is revised to **September 30, 2026**.

Rhode Island Department of Transportation

Addendum No. 1 – Ashton Viaduct Repairs (Bridge No. 027501)